

Fig. 1a




Fig. 1b




Fig. 1c




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7





Fig. 8



Schnitt A-A







Fig. 9Fig. 10

BEST AVAILABLE COPY

Spring rate

Fig. 11: Federrate

6/6

Spring rate in kN/mm per cm<sup>2</sup>  
Federrate in kN/mm pro cm<sup>2</sup>

